








Hammock




FRPE513.001









Nr	#	Type	Progr.	Volgnr	Bew.	Rev.	Benaming	Opmerking
1	1	MOD	FRP	371	006	A	Hangmat	Freeplay



Benaming
Title Hangmat

Opmerking
Comment Freeplay

Datum
Date 12-8-2011

Tekening
Drawing

TOE FRP 513 001

Modules Modules

FRPE513.001

Hammock

LOGBOOK

(Onderstaand logboek kan gebruikt worden om te voldoen aan de eisen, gesteld in artikel 14 van het Warenwetbesluit Attractie- en Speeltoestellen)

Type indication	Free Play
Product code	FRPE513.001
Name of equipment	Hangmat
Maximum height of fall	0,8 m
Year of construction	2017
Certificate	130061
inspection authority	Keurmerkinstituut Groeneweg 2e, Zoetermeer - 2718AA Zoetermeer
Name manufacturer	BOERplay Hyacintstraat 2 - 4255 HX Nieuwendijk Phone: +31 (0)183 40 23 66 Fax: +31 (0)183 40 35 64
name installer	
Description of equipment	Hammock
Location of equipment	
Data about the owner of the play equipment	
Name:	
Address:	
Postcode and town:	
Contact person:	
Telephone number:	
Data about the administrator of the play equipment	
Name:	
Address:	
Postcode and town:	
Contact person:	
Telephone number:	

LOGBOOK

Inspection and maintenance intervals



Nr.	Inspection	Maintenance	months between inspections
1	Verify equipment's stability, junctions and missing parts. Inspect bolts, screws and nuts for absence, jams, corrosion and wear.	Add missing parts, secure joints, apply missing fixing agent and replace corroded parts.	1
2	Check suspension for wear.	Replace worn parts and/or remove non-functioning parts.	1
3	Inspect rotating parts such as hinges, rolling-element bearings, etc. for wear and acceptability.	Replace worn parts and/or remove non-functioning parts.	1
4	Check wood for splinters, unacceptable damage and signs of rot. Especially at ground level.	Repair damage. Replace affected wood. Smoothen splintered wood and sharp edges.	1
5	Inspect foundation for stability, tearing and coverage.	Restore foundation and covering material.	3
6	Examine rubber and synthetic parts for wear, damage and break.	Replace original parts.	3
7	Inspect metal for corrosion and damage in the coating.	Restore any damaged coating (after removing rust and applying primer).	6
8	Check ropes, cables, chains and nets for wear and damage. Steel cables and nets which are tensioned must be checked for tension.	Replace parts where necessary. Steel cables and nets must be tensioned.	3
9	Inspect equipment for unsafe changes and additions.	Remove unsafe additions and correct unsafe changes.	1
10	Inspect safety surfaces.	Restore and repair where necessary.	1

Remarks

1. If used intensively, all points require extra attention.
2. Extreme weather conditions and locations may require a higher inspection frequency. Discuss this with the supplier.
3. Vandalism-sensitive locations require stricter inspections, possibly daily.
4. Check the terrain regularly for items that do not belong there, are unsafe or may be used wrongly. Examples are poisonous plants, glass shards, etc. Frequency depends on strain.
5. Remember that bad maintenance leads to unsafe conditions and notably faster impoverishment of the playground area.
6. Replacement parts can be ordered at the manufacturer with the part numbers on the module drawing. Drawings can be found in the user guide.
7. The impact area shall be provided with impact attenuating surface according to the specified falling height.
8. This list is conform the CEN-standard "playground equipment and surfacing NEN-EN 1176-7".

Certificaat


KEURMERKINSTITUUT

Warenwetbesluit attractie- en speeltoestellen


Certificaat van goedkeuring afgegeven door Keurmerkinstituut (aangewezen bij ministeriële beschikking van 8 juni 2004, VGB/P&L 2478562).

Certificaat nr.:	130061	Serie / Enkel
Dossier nr.:	7158	S
Betreft:	Hangmat Freeplay	
Aanduidingen:	37.1.513	
Eigenaar/houder:	Boer speeltoestellen b.v. Postbus 10 4255 ZG Nieuwendijk	
Soort toestel:	Wiebelnet tussen metalen staanders, valhoogte 84 cm	
Fabrikant:	Boer speeltoestellen b.v., Nieuwendijk	
Jaar van fabricage:	2010	
Leverancier:	Boer speeltoestellen b.v., Nieuwendijk	
Jaar van leverantie:	2010	
Datum keuring:	18 oktober 2010	

Keurmerkinstituut, Groeneweg 2 te Zoetermeer, verklaart dat het bovenvermelde toestel voldoet aan de vervaardigingsvoorschriften genoemd in het Warenwetbesluit attractie- en speeltoestellen (Staatsblad 474, 27 september 1996). Beoordelingscriteria EN 1176-1:2008, EN 1177:2008.



drs. W. van Weperen
directeur



Nr	#	Type	Progr.	Volgnr	Bew.	Rev.	Benaming	Opmerking
1	4	BSR	011	012	025		Borgdopmoer	M12 - RVS A2-70
2	4	BSR	030	012	003		Sluitring	M12 - RVS A2-70
3	4	BSR	040	012	120		Oogbout ~DIN 580	M12 x 120 - RVS A2-70
4	6	BSV	010	010	010		Borgmoer	M10 - VZ 8.8
5	4	BSV	021	010	130		Zeskantbout ISO 4014	M10 x 130 - VZ 8.8
6	2	BSV	021	010	120		Zeskantbout ISO 4014	M10 x 120 - VZ 8.8
7	12	BSV	030	010	002		Sluitring	M10 - VZ 8.8
8	8	KST	DON	011	050		interplay donut	blauw
9	8	KST	DOP	011	050		interplay dop	blauw
10	2	OME	VRB	903	VZP	C	Voetplaat	100 x 100
11	2	ORE	FRP	009	100	D	Rebo 1800	Paal 99x99
12	2	SME	FRP	005	618		Steunpoot Rechts	Hangmat
13	2	SME	FRP	006	618		Steunpoot Links	Hangmat
14	1	SNT	FRP	001			Net hangmat	SMB